Appendix C		
Town and Community Councils - Resurfacing requests 2018	Comments	Plan Ref No.
Barry Town Council		
Currently nothing received		
Colwinston		
Twmpath Lane - in particular from Twmpath Grange down to the Village boundary sign	Included under Resurfacing Works - score 170	88
Junction coming from Crack Hill right down past the school, which has deteriorated dramatically since the Redrow Development	Included under Resurfacing Works - score 160	91
Road from the Village down to Llysworney - from Rose Cottage to Llysworney via Hilton - this road has collapsed	Included under Resurfacing Works - score 155	96
Cowbridge with Llanblethian Town Council		
(Cowbridge / Aberthin) A4222 between Aberthin and the crossroads at the top of Cowbridge High Street (Traffic Lights)	Included under Resurfacing Works - score 305	11
(Llanblethian) Church Road Llanblethian from the Cross Inn down to the Church	Included under Resurfacing Works - score 260	43
(Cowbridge) Eastgate from the traffic lights down to the Town Hall	Included under Resurfacing Works - score 170	89
(Llanblethian) Broadway from junction with Windmill Lane to junction with Castle Hill	Included under Resurfacing Works - score 160	92
(Cowbridge) Church Street from High Street to and including the South Gate arch	Included under Resurfacing Works - score 135	102

		1
	Included under Resurfacing	
(Llanblethian) Love Lane	Works - score 135	103
	Included under Resurfacing	
(Llanblethian) Factory Road	Works - score 130	106
	Included under Resurfacing	
(Cowbridge) High Street up Westgate (junction of Llantwit Major Road)	Works - score 240	51
(Cowbridge / Llanblethian) Large pothole at the junction of Constitution Hill with Love Lane	Pothole defect repaired	n/a
Dinas Powys		
	Included under Resurfacing	
	Works - score 345 - on hold	
A4055 (Cardiff Road)	potentail gas utility works	3
	Included on Micro-asphalt	
Plas Essyllt Through to Castle Drive	works list	141
	Included under Resurfacing	
Pen-y-Turnpike (mainly falls under Michaelston / Leckwith	Works - score 300	18
Ewenny		
	Included under Resurfacing	
well surfaced	Works - score 105	112
Wick Road (From the Village Stores to Beech Court Farm) - this is a very well used road and there is a	Included under Resurfacing	
play area on this road. It is also on the National Cycle Network	Works - score 185	83
Abbey Road (from bottom Lodge to the Church) - there are water issues here which the Council is	Condition assessed and not	
aware of which have affected the road surface. This road leads to a historic monument and is used by	considered priority under	
a large number of visitors. The road also leads to the Parish Church which holds regular services	current Plan	n/a

The road to Ogmore by Sea (B4524) by Ewenny Cross - this is a well used major route. There is also a	•	
residential care home off this road	Works - score 270	39
The junction of Wick Road onto Ewenny Road up to the Bridgend Boundary (B4265) - this is a very well	•	
used busy road	Works - score 185	83
	Outside scope of resurfacing	
Resurfacing of the verge from the Pavillion to the A48	plan	n/a
Llancarfan		
	Refers to various highway	
	issues to be responded	
See letter dated 27/02/2018 to Mike Clogg advising of highway issues	seprately	Refer 30 & 47
Llandough		
Llandough Hill - The condition of the road is very poor, it is a public transport route and is well used as a	Included under Resurfacing	
means of gaining access to and leaving the community of Llandough. The traffic calming road hump on	Works - score 195; road	
the hill has partly disintegrated and could be dealt with as part of the resurfacing	hump to be inspected and	
	repaired	73
Llandow		
The road at the entrance to village of Llandow, if approaching from Rectory Cross which runs parallel to	Included under Resurfacing	
Paes-y-Fro	Works - score 210	70
	Included under Resurfacing	
The road from Moor's Head Farm, Sigingstone to its junction with the B4270 Llantwit Major Road	Works - score 190	77
The road from Llysworney Village which leaves the B4268 and proceeds in an easterly direction via	Included under Resurfacing	
Crossways to its junction with the B4270 near the Cross Inn / Lane to Llanfrynach	Works - score 215	64
· · · · · ·		
Llanfair		
Currently nothing received		

Llangan		
The road from the former Ruthin Chapel which leads to St Mary Hill Church - complaints about this road		
had been made for a number of years. The distress and issues this road causes for funerals and	Included under Resurfacing	
weddings as well as normal Church attendance is extensive	Works - score 220	59
	Included under Resurfacing	
Road between Llangan and Treoes - snow has damaged this road and it is the main through route	Works - score 220	60
Unnamed road from A48 at Crack Hill to Llangan - in parts the whole edge of the road has sunk by	To be inspected separately	
about 40 FMS. This is getting worse as lorries deliver and collect from Pheasant Acre nursery and land	-	,
in the area is being used by farmers from Brocastle who bring machinery this way	identified as approriate.	n/a
Llanmaes		
(Map 1 Attached to letter) - Road leading North East out of the village from Pensarn Bungalow towards	Included under Resurfacing	
St Mary Church	Works - score 215	63
	Included under Resurfacing	
	Works - score 215; consider	
(Map 2 Attached to letter) - Road leading East out of the village from Mill Cottage to Millands Park	works programme for NAR	65
Llantwit Major Town Council		
	Included under Resurfacing	
East Street, leading from Durrell Street, around the Strand and along to the Cenotaph at the Square	Works - score 225	56
	Condition assessed and not	
The road leading to West Gate Entrance, MOD St Athan and the majority of the roads in the Bird Estate	considered priority under	
(West Camp)	current Plan	n/a
	Included under Resurfacing	
The Eglwys Brewis Road from the B4265 junction	Works - score 295	26
The Eglwys Brewis Road from the B4265 junction	Included under Resurfacing	

Michaelston Le Pit and Leckwith		
	Included under Resurfacing	
Woodlands Lane, Leckwith. It is heavily potholed with some subsidence	Works - score 190	78
The ten and of the monthlinte Michaelstein to Dit forms Denier Tennedity Deniet between Denier Tennedity and	la shuda duur dan Dasurfa sin n	
The top end of the road into Michaelston le Pit form Pen-y-Turnpike Road between Pen-y-Turnpike and	Ţ.	
the car park	Works - score 290	29
Note further letter of 16/01/2019 eduicing that checkute priority be given to require ourfeeing of length of Dep	Included under Decurfacing	
Note further letter of 16/04/2018 advising that absolute priority be given to re-surfacing of length of Pen-		40
y-Turnpike Road running from Dinas Powys to Leckwith Road.	Works - score 300	18
Penarth Town Council		
	Included under Resurfacing	
	Works - score 340; footway	
Stanwell Road	work to be coordinated	6
	work to be coordinated	0
	Included under Resurfacing	
Plymouth Road	Works - score 295	22
Tymouth Road	Included on Micro-asphalt	
Cornerswell Road	works list	124
Pendoylan		
•	Included under Resurfacing	
	Works - score 355; potential	
	coflict with housing	
The road up Pengelli Hill to Ty Fry Farm	development	2
	Included under Resurfacing	
The road from Clawdd Coch to Tyn-y-Plancau	Works - score 295	27
	Included under Resurfacing	
Pontsarn Lane	Works - score 200	71

Penllyn		
Ystradowen area - Resurfacing of the entrance to Badgers Brook estate via St. Owains Cr. From the A4222	Included under Resurfacing Works - score 160	94
Ystradowen area - Sandy Lane up to Highgrove. The road past Highgrove falls into Welsh St. Donat's CC	Included under Resurfacing Works - score 160	93
Llansannor, Newton area - There is significant flooding due to drains not being in order, the raising of the road surface over that area by say 100mm might assist in alleviating the problem	Not a resurfacing issue	n/a
Peterston-Super-Ely		
Chapel Lane	Included under Resurfacing Works - score 235	52
Pendoylan Road (Main road through the village from St Brides Super Ely to Gwern y Steeple)	Works previously undertaken to this route	n/a
Groesfaen Road	Included under Resurfacing Works - score 235	53
St Athan		
Currently nothing received		
St. Brides Major		
The road through Ogmore by Sea	Included under Resurfacing Works - score 175	87
The road between Watermill and the Pelican with severe potholes within that area, causing damage to vehicles	Included under Resurfacing Works - score 270	39

St. Donats		
	Included under Resurfacing	
The road between Marcross to Monknash	Works - score 255	45
	Included under Surface	
The road from the Llantwit Major / Wick Road to Splott Farm on both sides of the road	Dressing Works	157
	Included under Resurfacing	
The road between the junction of the Llantwit Road to end of Water Street via Monkton	Works - score 295	21
St. Georges and St. Brides-Super-Ely		
	Included under Resurfacing	
Heol St-y-Nyll which becomes impassable to residents on numerous occasions	Works - score 195	74
	Included under Resurfacing	
St. George's Super Ely main road - especially the section from the railway crossing to the Church	Works - score 215	66
St. Nicholas and Bonvilston		
Currently nothing received		
Sully and Lavernock		
	Included under Resurfacing	
Cog Rd from junction with South Rd to Swanbridge Rd	Works - score 160	90
	Included under Resurfacing	
Swanbridge Rd from junction with South Rd to Cog Rd	Works - score 240	48
	Included under Resurfacing	
Lavernock Rd from South Rd to junction with Westbourne Rd	Works - score 250	46

Wenvoe		
	Included under Resurfacing	
Old Port road - From Grange Close to bottom of Tarrws Lane	Works - score 160	95
	la aluda dura dan Dagunta sin n	
- ,	Included under Resurfacing	05
Tarrws Lane	Works - score 160	95
	Included under Resurfacing	
Walston Road	Works - score 160	95
		90
	Included under Resurfacing	
St. Lythans Road from Beili Farm (Councillor Bird) to the Humpback Bridge	Works - score 220	61
		01
Wick		
Currently nothing received		
Iltydd Ward Members (Barry)		
	Included under Resurfacing	
Pontypridd Road	Works - score 185	84
	Included under Decurfacing	
	Included under Resurfacing	
	Works - score 325; on hold	
	potential Welsh Water utility	7
Port Road West	issues	7
	Condition assessed and not	
	considered priority under	
Jenner Road	current Plan	n/a
	Included under Desurfacier	
	Included under Resurfacing	00
Dudley Place	Works - score 295	28